

TECHNICAL DATASHEET

Vitralit® UV 2415

Vitralit UV curing products are single component adhesives that cure very quickly under UV or even visible light sources. These products are very well suited for applications in automotive, electronic, optical, or glass applications or for conformal coatings. They are based on modified Acrylic-polyurethane.

Vitralit 2415 Applications: Bonding/ Sealing/ Encapsulation of plastics as well as glass, metals or FR4 to protect sensitive parts against mechanical and environmental stresses. Further Properties: toughened, dry surface, very fast curing, very good temperature- and chemical resistance.

Shelf life

Store in original, unopened containers for 6 months at max. 25°C

Technical Data

klar g	jelblich
1	acrylat

UNCURED PROPERTIES

/	UPM)	PE-Norm P001	1500 to 2500
		PE-Norm P050	> 100
		PE-Norm P051	approx. 1.1
		PE-Norm P018	1.5
		PE-Norm P002	5
		PE-Norm P037	20
	/	/ UPM)	PE-Norm P050 PE-Norm P018 PE-Norm P018

CURED PROPERTIES

Temperature Resistance [°C]		
Hardness Shore D	PE-Norm P052	65 to 75
Water Absorption [Gew-%]	PE-Norm P053	< 0,2

Our data sheets have been compiled to the best of our knowledge. The information included in our data sheets is exclusive information for the tended user and describes characteristics, with no declaration of commitment. We recommend trials in order to confirm that our products satisfy the particular application requirements. For an additional technical consultation, please contact our RD department. In general, for guarantee claims, please refer to our standard terms and conditions.

Adhesives and more...

XP.08.80



TECHNICAL DATASHEET

Vitralit® UV 2415

mechanical data

Compression Shear Strength (Glass/Glass) [MPa]	[PE-Norm P061]	approx. 9
Compression Shear Strength (Glas/Aul) [MPa]	[PE-Norm P061]	approx. 8
Compression Shear Strength (Glass/Stainless Steel) [M	∕/P {[PE-Norm P061]	approx. 8
Lap Shear Strength (PC/Edelstahl) [MPa]	[PE-Norm P013]	approx. 6
Lap Shear Strength (PC Alu) [MPa]	[PE-Norm P013]	approx. 6
Lap Shear Strength (PMMA/PMMA) [MPa]	[PE-Norm P013]	approx. 4
Elongation at Break [%]	[PE-Norm P060]	approx. 46

Instructions for Use

Surface Preparation

The surfaces to be adhered should be free of dust, oil, fat or any other dirt in order to optimise reproducible bonds. Lightly soiled surfaces can be cleaned with cleaner IP, whereas substrates with low surface energy (such as polyethylene, polypropylene or Teflon) need to be treated physically using plasma or corona

to create a suitable working surface. For glass bonding applications we have developed a special primer pen which can be easy applied to prepare the surface for best results. Application

Our products are delivered ready for use. As soon as you receive them, you can dispense them, be it by hand from the container, or semi/fully automatically. When applied automatically, we recommend the use of air pressure with the appropriate cartridge/piston combination to dispense the adhesive at the required speed and accuracy. If help is required, please consult our engineering department

Please read the corresponding **Safety Data Sheet** for this product.

Adhesives and more...